

COPY  
XEROX

10

BLACK SHIELD CHECK LIST  
(As of 14 Jul 67; with tankers)

Code Name BX-6714 Mission Nr 14 Date 15APR67 H-hour 0225Z 1125L

Msn Pilot		A Fcstr	D. B.	Duty Hours	10-18, 06-18L
Spare Pilot		B Fcstr	D. M.	Duty Hours	
Chase Pilot		C Fcstr	J. Y.	Duty Hours	

Msn Coord	A Obsvr	Duty Hours
Msn DCOM	B Obsvr	Duty Hours
Msn TTFC	C Obsvr	Duty Hours

H-Minus	ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-24:00	Start this check list	B-3		0225	1125	1100	DM
-24:00	Arrange work schedule	B-4		0225	1125	—	—
-23:30	Attend Commander's Briefing	B-1		0400	1300	—	—
-23:00	Rcv [REDACTED] (Prelim Ops Data)	B-1		0325	1225	—	—
-22:30	Coordinate TTFC support	B-2		0355	1255		
	Give prelim data to TTFC	[REDACTED]	B-2	0300 0400	1200 1300		
-21:00	Rcv [REDACTED] (Tmml fcsts)	B-5		0525	1425	1315	WFB
-21:00	Start Met Watch on wall map	B-21		0525	1425		
-21:00	Rcv [REDACTED] (Mission wx data)	B-6		0525	1425	1345	[REDACTED]
	Pick up APT pictures	B-10		0530	1430		
	Rcv [REDACTED] (Composite rte data)	B-6		Vrbl	Vrbl		
-17:30	Rcv [REDACTED] Amend (Mission wx)	B-6		0855	1755		
-17:15	Rcv [REDACTED] (Tmml fcsts)	B-5		0910	1810		
-17:00	Brief pilot and ops staff	B-7		0925	1825		
-14:00	Rcv letdown plates from DCOM	B-14		1225	2125		
-14:00	Rcv [REDACTED] (Tanker msn wx fcst)	B-9		1225	2125		
	Letdown plates to DCO	B-14		1300	2200		
	Rcv [REDACTED] (Final Ops data)	B-8		1330	2230		

Cancelled replaced  
by 376715

25X1A

## BLACK SHIELD CHECK LIST (as of 14 Jul 67)

Page 2

	H-Minus	ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY Initials
25X1A	-10:00	Send [REDACTED] (Terminal wx fcsts)	B-5		1625	0125		
	-9:00	Rcv [REDACTED] (GO-NO GO wx fcsts)	B-11		1725	0225		
25X1A	-9:00	Give [REDACTED] input to Msn Coord	B-23		1725	0225		
	-8:00	Send [REDACTED] (thru L-hr, if reqd)	B-16		1825	0325		
		Annotate tanker DD Forms 175	B-24					
		Brief tankers	B-24					
25X1A	-4:00	Send [REDACTED] (Terminal wx fcsts)	B-5		2225	0725		
	-4:00	Send [REDACTED] (Met Watch obs)	B-18		2225	0725		
		Brief tankers	B-24					
	-3:30	Brief pilots and ops staff	B-20		2255	0755		
25X1A		Brief tankers	B-24					
	-3:00	Rcv [REDACTED] Amend (GO/NO GO fcsts)	B-11		2325	0825		
	-3:00	Rcv Letdown Plates from DCO	B-14		2325	0825		
	-3:00	Enter fcsts on Letdown Plates	B-14		2325	0825		
	-2:30	Msn Obsvr to CP; posts data	B-13		2355	0855		
25X1A	-2:00	Rcv [REDACTED] (Wx Scout reports)	B-22		0025	0925		
		Pick up APT pictures	B-10		0000	0900 or ASAP	or ASAP	
	-1:40	Msn Festr to CP; Obsvr to wx str	B-13		0045	0945		
	-1:35	Letdown plate fcsts to pilots (Notify Mission Coordinator)	B-14		0050	0950		
	-1:30	Notify DCOL (If need to rebrief pilots)	B-20		0055	0955		
	-1:10	Rebrief pilots if necessary	B-20		0115	1015		
L-Plus		Landing time: Z L						
	+0:15	Return Met Watch to wx station	B-13					
	+0:15	Start debriefing form	B-15					
	+0:45	Attend pilot debriefing	B-15					
25X1A	ASAP	Give [REDACTED] input to DCOM Coord after debriefing	B-15		ASAP	ASAP		
	+24:00	Turn in Msn Wx File to Intell	B-17					